1965 JAN 4

5 JAN 1965

P Ø42Ø34Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4Ø8Ø STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEAHQ/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 36Ø2.

COPIES RECEIVED Office Act. Rech CyNo. 21 Master File O\$ ADMIN SEC BR P&DS CSD IFD PD PSD TID PAG CIA/PID DIAXX-4 NSA LO DIAAP

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF CEOR

- 1. CAMERA B 15 WAS USED IN MISSION 3980 FLOWN ON 31 DEC 4.5
 PROCESSING WAS ACCOMPLISHED BY NAVRECONTECHSUPPCEN.
 - 2. ORIGINAL NEGATIVE:
 - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: THERE ARE SEVERAL FINE, LONGITUDINAL PLUS DENSITY
 STREAKS THROUGHOUT THE MISSION. THE TWO MOST PRONOUNCED AND CONSISTENT
 STREAKS ARE 3.3" AND 4.75" FROM THE INBOARD EDGE OF THE FILM.
 THERE IS MINOR OUTBOARD ROLLER CHATTER IN THE BOARDER OF THE FIRST
 250 FRAMES. THERE IS A MANUFACTURING SPLICE ON FRAME 1291 AND A
 HEAT SPLICE ON FRAME 1320. THERE ARE HANDLING MARKS ASSOCIATED
 WITH THE HEAT SPLICE.
- C. 9L SIDE: THERE IS A MANUFACTURING SPLICE ON FRAMES 1711 AND 2141 AND A HEAT SPLICE ON FRAME 1310.
- D. BOTH SIDES: INBOARD ROLLER CHATTER IS CONTINUOUS
 THROUGHOUT THE MISSION. EDGE FOG IS CONTINUOUS ALONG BOTH FILM

cange 1
canging automatic
spragrating and
chars its aid

EDGES ON THE PHOTOGRAPHY OF BOTH CAMERAS. THE SECURITY CLASSIFICATION OF THE FILM IS NOT PRINTED ON THE LEADER OR TRAILER OF THE FILM.

THE FRAMES OF BOTH CAMERAS ARE TITLED Ø1-2608.

- E. THERE WERE NO APPARENT CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.
 - 3. POSITIVE:
 - A. PRINTING AND PROCESSING WERE GOOD.
 - B. PI SUITABILITY IS GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 15 PERCENT OF THE MISSION.

SECRET

-END OF MESSAGE-